

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

SMITH FARM, BARN
399 Ebey Road
Coupeville vicinity
Island County
Washington

HABS WA-249-A

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Anne E. Kidd, photographer, April 2006

- | | |
|------------|---|
| WA-249-A-1 | BARN EXTERIOR PERSPECTIVE OF SOUTH AND EAST FAÇADES, LOOKING WEST. (This image shows the barn's hip-on-gable roof with the mid-1950s and early 1970s shed additions on its north side.) |
| WA-249-A-2 | BARN EXTERIOR PERSPECTIVE OF WEST FAÇADE FROM ACCESS ROAD, LOOKING EAST. (A shed addition was added to the north end of the barn in the mid-1950s for squash storage. Another addition was built in the early 1970s to provide feeding and watering troughs for cattle. This image also shows the granary, on the right.) |
| WA-249-A-3 | INTERIOR OF SOUTHWEST CORNER, LOOKING WEST WITH CARRIAGE STORED IN HAY LOFT. (The barn's wide truss span allowed for an open floor plan. This was originally divided into three distinct spaces: milking stanchions, loose hay storage, and horse stalls.) |
| WA-249-A-4 | INTERIOR SHOWING POST AND BEAM CONSTRUCTION AND TRUSS CONFIGURATION LOOKING WEST. (The barn's plank floor was removed due to decay and rot. The barn now has a dirt floor.) |